

1. Print this PDF at 100% scale.
2. Remove existing dust boot and tools
3. Hold up to bottom of the spindle without tool.
4. If spindle aligns centered on the "spindle opening" and pneumatic rods fit one of two holes up you have a match with our dust boot!
5. Note which mount opening (A or B) fits best.



PORTLAND CNC
LAGUNA DUST BOOT
FIT DIAGRAM

pdxcnc.com